
Chief Architect Premier X9
File Edit Build Terrain Library 3D CAD Tools View Window Help
Camera View Set
Using Active Defaults
Untitled 1: Floor Plan
Untitled 1: Cross Section/Elevation - Elevation 1
Untitled 1: Perspective Full Overview - Camera 1
Untitled 1: Perspective Full Overview - Camera 1
TWO SEPARATE MOLDINGS PRESENT A PROBLEM BECAUSE THE GABLE EXTENDS PAST THE EAVE....
SINGLE MOLDING CHANGING AN ANGLE PRESENTS A PROBLEM BECAUSE THE PROFILES DON'T MATCH UP....
Done: 2920 surfaces
All Floors
X: 595 9/16", Y: -228 13/16", Z: 55 7/8"
Time: 0.01 secs
1822 x 821