Scaling a Picture to Full Size Using the Rescaling Technique

- Import the Image
- Stretch is close to full size
- Add a CAD Line/Box with dimensions turned on
- Use the Formula
- Click on Image
- Open Transform Replicate
- Add Scale Factor in Resize
- Check using CAD Line

- 1.) CAD Line Length (Converted to Inches)
- 2.) Length Desired (Converted to Inches)

Length Desired
DIVIDED BY

Length of Existing

= Scale Factor